

Prepared by and return to: Linn County Secondary Road Department, 1888 County Home Road, Marion, Iowa 52302, (319)892-6400

RESOLUTION # 2018-11-164

ESTABLISH SPEED LIMIT

WHEREAS, portions of Indian Hill Road are in Cedar Rapids and unincorporated Linn County, and

WHEREAS, the Board of Supervisors is empowered under authority of the Iowa Code Sections 321.255 and 321.285 of the Code of Iowa, to determine upon the basis of an engineering and traffic investigation, that the speed limit of any secondary road is greater than is reasonable and proper under the conditions existing, and may determine and declare a reasonable and proper speed limit, and

WHEREAS, such an investigation has been requested and has been completed by the Linn County Engineer, and

WHEREAS, the Board of Supervisors directs the Linn County Engineer to establish a speed limit that falls below the recommended speed.

NOW THEREFORE, BE IT RESOLVED BY THE BOARD OF SUPERVISORS OF LINN COUNTY that the speed limit be established and appropriate signs be erected at the location described as follows:

- 30 mph on Indian Hill Road from Cottage Grove Ave SE to 30th Street Dr SE in sections 12 & 13-83-7.

Resolution adopted this 7 day of Nov., 2018

Linn County Board of Supervisors

[Signature]
Chairperson

[Signature]
Vice Chairperson

[Signature]
Supervisor

[Signature]
Supervisor

[Signature]
Supervisor

ATTEST:

[Signature]
Linn County Auditor
[Signature]
Deputy

Speed Limit Resolution

Indian Hill Road
30 mph

